

HISTORIC AMERICAN BUILDINGS SURVEY  
INDEX TO PHOTOGRAPHS

HABS  
MICH.  
82- DETROIT,  
42-

Union Trust Building (Guardian Building)  
500 Griswold St.  
Detroit  
Wayne County  
Michigan

HABS No. MI-273

Allen Stross, Photographer, June 1979

- MI-273-1      EXTERIOR, AERIAL VIEW OF UNION TRUST BUILDING
- MI-273-2      EXTERIOR, TOP OF BUILDING SHOWING TERRA COTTA DECORATION ON TOWER
- MI-273-3      EXTERIOR, FRONT ENTRANCE
- MI-273-4      EXTERIOR, DETAIL OF STONWORK ABOVE ENTRANCE DOORS
- MI-273-5      INTERIOR, LOBBY, LOOKING TOWARD BANK SHOWING STAIRS WITH  
METAL RAILING, SCREEN AND CLOCK
- MI-273-6      INTERIOR, LOBBY, LOOKING TOWARD SECURITY DESK AND ELEVATORS
- MI-273-7      INTERIOR, LOBBY, SECURITY DESK, CLOSE-UP SHOWING BACKGROUND WALL  
ORNAMENTATION
- MI-273-8      INTERIOR, LOBBY. LOOKING FROM BANK TOWARD ENTRANCE
- MI-273-9      INTERIOR, DETAIL OF SCREEN SEPARATING BANKING ROOM FROM LOBBY
- MI-273-10     INTERIOR, BANKING ROOM, LOOKING TOWARD METAL SCREEN AND LOBBY
- MI-273-11     INTERIOR, BANKING ROOM CEILING SHOWING ELABORATE TILE ORNAMENTATION
- MI-273-12     INTERIOR, BANKING ROOM WALL MURALS
- MI-273-13     INTERIOR, BASEMENT, ORIGINALLY SAFETY DEPOSIT AREA, SHOWING METAL  
GATES AND TELLER CAGE
- MI-273-14     INTERIOR, BASEMENT, METAL GATES
- MI-273-15     INTERIOR, BASEMENT, ORIGINAL CHECK WRITING DESK